

TH169DR / TH167DR.
Ploaf arm Rework.

Pre 10/2001

measure 50mm from pivot and
bend down 25°

leave this bend untouched.

(Scale 1:1).

increase existing be
to 60°

LRA Configured

Straighten out
OEI bend this
will increase ploaf
arm length.

OEI Configuration.

